


<b>AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT</b>			1. Contract Number	Page of Pages 1   4
2. Amendment/Modification Number DCAM-2008-B-0014-003	3. Effective Date 11/30/2007	4. Requisition/Purchase Request No.	5. Solicitation Caption Eastern Market Rehabilitation	
6. Issued By: Office of Contracting and Procurement Construction, Design, Building, and Renovation 441 4th Street, NW Washington, DC 20001		Code	7. Administered By (If other than line 6)	
8. Name and Address of Contractor (No. Street, city, country, state and ZIP Code)			(X) 9A. Amendment of Solicitation No. DCAM-2008-B-0014	9B. Dated (See Item 11) 10/31/2007
Code			10A. Modification of Contract/Order No.	
Facility			10B. Dated (See Item 13)	
<b>11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS</b>				
<input checked="" type="checkbox"/> The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offers <input type="checkbox"/> is extended. <input checked="" type="checkbox"/> is not extended. Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing Items 8 and 15, and returning <u>2</u> copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or fax which includes a reference to the solicitation and amendment number. FAILURE OF YOUR ACKNOWLEDGEMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by letter or fax, provided each letter or telegram makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.				
12. Accounting and Appropriation Data (If Required)				
<b>13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14</b>				
A. This change order is issued pursuant to: (Specify Authority) The changes set forth in Item 14 are made in the contract/order no. in item 10A.				
B. The above numbered contract/order is modified to reflect the administrative changes (such as changes in paying office, appropriation date, etc.) set forth in item 14, pursuant to the authority of 27 DCMR, Chapter 36, Section 3601.2.				
C. This supplemental agreement is entered into pursuant to authority of:				
D. Other (Specify type of modification and authority)				
E. IMPORTANT: Contractor <input type="checkbox"/> is not, <input type="checkbox"/> is required to sign this document and return <u>2</u> copies to the issuing office.				
14. Description of amendment/modification (Organized by UCF Section headings, including solicitation/contract subject matter where feasible.)				
The subject solicitation is hereby amended as follows:  Responses to bidder's questions - Attachment A				
Except as provided herein, all terms and conditions of the document referenced in Item (9A or 10A) remain unchanged and in full force and effect				
15A. Name and Title of Signer (Type or print)			16A. Name of Contracting Officer Karen Hester	
15B. Name of Contractor	15C. Date Signed	16B. District of Columbia	16C. Date Signed	
(Signature of person authorized to sign)			11/30/07	
			(Signature of Contracting Officer)	

EASTERN MARKET REHABILITATION  
 IFB No. DCAM-2008-B-0014  
 225 7<sup>th</sup> Street SE, Washington, DC

29 November 2007

AE Response to Bidders Questions

No.	Bidders Question	AE Response
1	Drawing A102 Note 12-01 states "Provide portable gallery walls" however there are no specifications for this item. Please provide clarification as soon as possible.	Basis of design product: DIRTT Solid Movable Wall system, 4'-0" wide x 8'-0" high solid panels with powder coated aluminum extrusions, color to be selected by COTR from manufacturer's standard color range; fabric wrapped tiles, color to be selected by COTR from manufacturer's standard color range; and hidden zipper or angled/pivot zipper panel connections.
2	There are four details show on drawing S 202, detail 1,2,5 and 6, but no references to where these details are coming from. It is difficult to identity, which detail are coming from, or,etc. Please advise.	<p>These are typical details. Existing steel beams in South Hall First Floor framing plan are to be repaired or replaced per Sheet S102, Table "Estimated Repairs", and typical note called out on plan 1/S102 at sheet location P7.</p> <p>Sheet S102, Table "Estimated Repairs"          - Type 3 - change description to read "Repair Exist. Bms. Per 1/S202."</p> <p>Sheet S102, Table "Estimated Repairs"          - Type 4 - change description to read "Repair Exist. Bms. Per 2/S202."</p> <p>On Sheet S102, Detail 1 – at sheet location M15, change note to read "Infill historic wood hatches per 5/S202."</p> <p>On Sheet S102, Detail 1 - at grid locations M6 &amp; M13 - change detail reference 10/S200 cut through the two ramps at the east side of the South Hall to read "6/S202".</p>
3	Drawing A 404 E1 Basement Elevator Plan has a reference A-9 / A 404. There is no A-9/ A 404 in the contract document. Please advise.	In drawings A1, E1, and K1, change reference "A9/A404" to "A8/A404".
4	Drawing A102 Note 11-01 calls for three (3) 38" x 38" carts however no specifications are given for these carts. Please provide more information for these items.	These carts are specified in Spec Section 116124 Portable Dance Floors, Paragraph 2.4.B "Storage Trucks".

EASTERN MARKET REHABILITATION  
 IFB No. DCAM-2008-B-0014  
 225 7<sup>th</sup> Street SE, Washington, DC

29 November 2007

No.	Bidders Question	AE Response
5	Please provide the soil borings and soil report for this job site?	No geotechnical work has been undertaken.
6	Drawing S102--BM Repair & Topping Replacement (Typ) 9"1" Please clarify these 2 drawing annotations?	Existing steel beams in South Hall First Floor framing plan are to be repaired or replaced per Sheet S102, Table "Estimated Repairs", and typical note called out on plan 1/S102 at sheet location P7. See response to Bidders Question #2 above for clarification of the detail references. The beams are Historic 9-inch deep "I" beams shapes [9"I" (TYP)].
7	When the 1st floor topping is removed is it the intention to remove the wood decking?	There is no wood decking.
8	In the first floor north is the existing Slab on grade to be removed or converted over?	The existing Slab on Grade will be removed and replaced. See A1/A102 Note 1. Refer to 1/S200 for typical slab on grade detail. See A405 & A406 for concrete floor pattern.
9	Drawing S101--Existing Post 24 x 24 footing to be removed see 1 & 2 / 5200 (TYP UNO) if this is done what will hold the floor above when it is fully loaded?	The replacement concrete slab above the brick arch is to be reinforced, existing beams are to be repaired or replaced (see response to Bidders Question #2), and the existing brick arches between the beams are to be repointed, per Details 1 & 2 on S202 and the "Estimated Repairs" table on S102. Change the detail reference in the cited note to "See 1 & 2 on S202"
10	Fire plans show no pull stations by doors as per coded, will this be a change or is the building exempt?	DCRA review is not complete at this time. The bidder should bid the drawings as they are shown.

EASTERN MARKET REHABILITATION  
IFB No. DCAM-2008-B-0014  
29 November 2007  
Attachement A

11) Question: The estimated quantities for brick arch repointing shown on drawing S-102 are different from the areas shown on drawings A-151.

Response: In accordance with Section L.12 of the solicitation, all questions must be received ten (10) days prior to the bid opening on December 7. As this question was received past that date, unfortunately we are unable to answer your question.